

Laser Safety

Fire inside of a laser

- Please follow these steps in the event of a small fire
- If a fire is ever too large to handle using these steps, immediately locate the nearest lab staff.




1. Turn off the laser.
2. Open the lid.




3. Grab a spray bottle,
located on the wall.




4. Rapidly spray the fire.
5. Keep doing this until
the fire is out.



6. Remove the material
from the laser.



7. Clean up the area of ash
& debris.



8. Alert a staff member
as soon as possible.

- Always make sure you are using the proper settings & materials.
- Always make sure the inside of the laser is clear of debris before starting a laser job.